

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 4N, R 37E., W.M.

Corner Code No. X-21

Note: Monument marked as shown below


History of original corner establishment:

This corner was originally established by George S. Pershin, U.S. Deputy Surveyor, under Contract No. 322, dated July 29, 1879.

The original notes state:

Set fir post on South slope for 1/4 section corner, from which:

A fir 10 in. diam. bears East 34 links.
A spruce 10 in. diam. bears West 13 links.



Corner No.
Compass Declination: 18.0°

Description of corner evidence found:

Found a 2 1/2" brass cap on a 1 1/4" galvanized iron pipe 6" out of ground at fence corner with fences North and West. Corner located just North of road going NE-SW.

Description of monument and accessories established to perpetuate the original location of this corner:

Maintained corner by mounding with earth and stone.

Marked 4 new bearing trees:

A 9" lodge pole pine bears S 22°E, 28.8', scribed 1/4 S36 BT.
A 7" lodge pole pine bears S 53°W, 117.1', scribed 1/4 S35 BT.
A 10" white fir bears N 18 1/2°E, 27.2', scribed 1/4 S36 BT.
Southwest 9" fork of western larch school marm bears N 75 1/2°E, 45.9'.
Scribed 1/4 S36 BT. (measured to root crown)

Placed bearing object signs on all bearing trees.

Attached witness corner sign to railroad tie fence post 1' NW of corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

Date 9-91

Rec'd By XK

No. 91-75-C

★ OPO-786-276