

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 4 N R 37 E Y-14

	S	33
		■

DESCRIPTION OF CORNER EVIDENCE FOUND:
None found.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 27" in the ground, with 2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:


An 8" Engelmann Spruce bears North 6° West, a dist. of 7.70 feet, marked SE 1/16 S33 BT.
A 4" White Fir bears South 83° East, a dist. of 20.15 feet, marked SE 1/16 S33 BT.

Set steel fence post approx. 0.5 ft. South

Falls in remnants of North/South bearing fence line

I hereby certify that the corner was monumented December 2, 2025

Witness: Kyle Tucker



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2027

I use a tape and compass in the establishment of the new bearing trees. Bearings are measured from the center of the aluminum cap to a brass washer marked "OPLS 83571" tacked to the BT blaze using 14° East for declination. Distances are measured from the center of the aluminum cap to a 60D spike in the center right base of the tree.