

OREGON CORNER RESTORATION FORM

Section: 36

Township: 6 North

Range: 37 East

County: Umatilla

Date: August 21, 2001

Corner Designation: w-23.5

N.E. corner of West 1/2, S.W. 1/4, N.E. 1/4, Sec. 36

Previous Renewals/Surveys, etc.:

None

Monument(s) & Accessories Found (Condition & Source):

None

Monument Detail:

Monument Set (Procedures & Description):

5/8"x30" rebar with yellow cap stamped "Tomkins Surveying" set at protracted position within Section 36.

New Accessories:

- 1) Fence post and sign 0.3' East
- 2) 14" White Fir scribed "BT", sign attached bears N 23°W 18.3'
- 3) 14" Leaning White Fir scribed "BT", sign attached bears S 63°E 31.7'

Location & Comments:

Corner falls approximately 50' East of access road.

Compass Declination:

19° East

Firm/Agency: Tomkins Land Surveying, Inc.

20 E. Poplar, Suite 204  
Walla Walla WA 99362

Party Chief: Paul Tomkins

Notes:

Witness: Josh Davin

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Paul W. Tomkins*

OREGON  
JULY 26, 1988  
PAUL W. P. TOMKINS  
2360

*renews 6/30/02  
8/22/01*

RECEIVED BY

Umatilla County Surveyor

Date 8-01

Rec'd By JK

01-132-C