


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1881 by Meldrum & Campbell under General Land Office Contract No. 380.



Surveyor General Record States:

Set post for cor. to sects. 1-6-7-12. From which:

- A 18" Pine bears S 37 E, 10 lks.
- A 30" Pine bears S 55 W, 70 lks.
- A 40" Pine bears N 67 W, 50 lks.
- A 20" Pine bears N 61 E, 58 lks.

No record of subsequent remonumentation was found in County Records.

Description of corner evidence found:

Found original BT as follows:

A 43" Pine, poor condition, bears N67W, 33.0 ft., scribes visible.

No evidence of the BTs or post found.

Description of monument and accessories established to perpetuate the original location of this corner

At record bearing and distance from original BT, I set 2½"x30" iron pipe, with brass cap marked as shown, 25" in ground, from which:


New BTs

- A 9" Fir bears N67E, 5.7 ft. marked T6S R30E S6 BT.
- A 9" Fir bears S9E, 5.4 ft. marked T6S R30E S7 BT.
- A 8" Pine bears S56W, 39.5 ft. marked T6S R29E S12 BT.
- A 20" Fir bears N78W, 34.2 ft. marked T6S R29E S1 BT.

Nailed brass washer to BT blaze.

Set steel fence posts 5+ ft. North and 5+ ft. East of corner.  
Used steel tape and magnetic compass with 20° E declination.

Measured to face of blaze on original BTs and center of new BTs.



Office of Surveyor County of Umatilla  
 State of Oregon, I hereby certify that the within Instrument was filed in this office  
 for record on the 13 day of August, 1974  
*Ralph Thompson* by \_\_\_\_\_ (DEPUTY)  
 (COUNTY OFFICIAL)

E-2  
E-1

S-88-M