

LAND CORNER RECORD

5680-2

1. T. 6S R. 29E No. J-23 Cor. 1/4 Mer. W State Oregon <sup>(Rectangular)</sup> N. F. Umatilla <sup>LL</sup> Dist. Ukiah 19

2. Corner Status

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Corner is a post from which:  
 a. 6" Pine S. 05°W. 3 lks.  
 a. 8" Pine N. 09°W. 7 lks. ● *see mon. file, Brass Cap.*

7. Photo Identification  
 Photo No. EBI 2-63  
 Ident. By: KRJ

5. Investigation Notes:  
 Both B.T.'s found; scribing still visible, although both trees were dead and down. Location at stake checks with stump holes of original B.T.'s.  
 From FSRM to corner stake S. 30°W., 31.3 lks. distance. FSRM is 7" Ponderosa Pine, vigorous.  
 From FSRM to corner stake N. 58' E., 33 lks. distance. FSRM is 1 1/4" Western Larch, vigorous.  
 Fence runs S.W., is 30'E. of corner. Matlock Creek is 100' W. of corner on section line.  
 Red paint placed on corner stake and FSRM's.

8. Plane Coordinate Position Data  
 State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Field Book No. \_\_\_\_\_  
 Where Filed \_\_\_\_\_

9. Evaluation  
 Authentic \_\_\_\_\_  
 Needs Verif. \_\_\_\_\_ Monument NO  
 Re-estab. X Survey \_\_\_\_\_  
 Land Status Public Domain

6. Signed K.R. Johnson Title Forester Date 6-2-65

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By \_\_\_\_\_ Title \_\_\_\_\_

License \_\_\_\_\_ Agency \_\_\_\_\_ Date \_\_\_\_\_

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_  
(Agency)

(Date) (City) (County) (State)

14. Remarks:

J-23